








200



The front part of the board - lack veneer PCV.



200



200

